Blackstone River Coalition Watershed-wide Volunteer Water Quality Monitoring Program Report Card for 2016 Monitoring Season

| | | | | | | | Nestrions | |
|----------|------------------------------|-------------------------|------------|-------|----|---------------|-----------|------------------------------------|
| map # | Weter Body | Site Location | Acathotics | Tomn | DO | % Sat. | Nutrient | |
| # | WaterBody HEADWATERS TRIE | | Aesthetics | remp. | ЪО | % Sat. | S | |
| 1 | Kettle Brook | Stafford Street | | | | | | KEY TO COLOR |
| 2 | Dark Brook | Auburn High | | | | | | CODES |
| 3 | Tatnuck Brook cwf | VFW-south | | | | | | CODES |
| 4 | Tatnuck Brook *CWT | Park Ave. | | | | | | Excellent |
| 5 | Leesville Pond | Leesville inflow | | | | | | Good |
| 6 | Leesville Pond | Leesville outflow | | | | | | Fair |
| 7 | Beaver Brook | Jewish Community Center | | | | | | Poor |
| 8 | Beaver Brook | Park Ave. Carwash | | | | | | F 001 |
| 9 | Middle River | St. John's Cemetery | | | | | | |
| _ | Ararat Brook cwf | Ford Brook | | | | | | Onto monico |
| 11 | | Delaney Brook | | | | | | Categories |
| | Broad Meadow Brook | | | | | | | (Each category is derived from the |
| | Broad Meadow Brook | | | | | | | combination of the |
| | Broad Meadow Brook | | | | | | | following factors) |
| | Broad Meadow Brook | | | | | | | Tomoving radiordy |
| | Broad Meadow Brook | | | | | | | |
| 17 | Cold Spring Brook cw | | | | | | | Aesthetics - turbidity, |
| 18 | Quinsigamond River | | | | | | | water appearance, |
| 19 | Quinsigamond River | | | | | | | water appearance, |
| | Quinsigamond River | | | | | | | assesments |
| 21 | Quinsigamond River | | | | | | | Temp temperature |
| 22 | | Plantation Street | | | | | | DO - dissolved |
| 23 | | Roberto Clemente | | | | | | % Sat dissolved |
| | Sewall Brook cwf | School Street | | | | | | oxygen % saturation |
| 25 | Sewall Brook cwf | Holden Street | | | | | | Nutrients - nitrate & |
| 26 | Tilly Brook | Vinny Testa's | | | | | | orthophosphate |
| 27 | Bummitt Brook | Pratts Pond | | | | | | spiioopiiato |
| | | Sycamore Circle | | | | | | |

April 2017

^{** =} site experienced 1 or more no-flow conditions # = site experienced more than 2 missed sampling events



^{*}cwf = designated cold water fishery

Blackstone River Coalition Watershed-wide Volunteer Water Quality Monitoring Program Report Card for 2016 Monitoring Season

| map | | | | | | | Nutrient | |
|-----|----------------------------|------------------------------|------------|-------|----|--------|----------|------------------------------------|
| # | WaterBody | Site Location | Aesthetics | Temp. | DO | % Sat. | S | |
| | | | | | | | | |
| | BLACKSTONE RIVE | KEY TO COLOR | | | | | | |
| 29 | Blackstone River | Fisherville Pond Outlet/122A | | | | | | CODES |
| 30 | Blackstone River | Sutton St. USGS flow station | | | | | | |
| 31 | Blackstone River | Plummer's Landing | | | | | | Excellent |
| 32 | Blackstone River | Tow path / Stanley Woolen | | | | | | Good |
| 33 | Blackstone River | Upstream @Gorge/ Staples La | | | | | | Fair |
| 34 | Blackstone River | Main St. Blackstone/TKO | | | | | | Poor |
| 35 | Blackstone River | River Island Park | | | | | | |
| 36 | Blackstone River | Below Albion Dam | | | | | | |
| 37 | Blackstone River | Slater Mill | | | | | | |
| | TRIBUTARIES | | | | | | | Categories |
| 38 | Mumford River | Hotel Pond Outlet | | | | | | (Each category is derived from the |
| 39 | Mumford River | L. Manchaug Inlet | | | | | | combination of the |
| 40 | Mumford River | L. Manchaug Out./Parker Rd | | | | | | following factors) |
| 41 | Mumford River | Gilboa Street/above WWTP | | | | | | Tollowing factors ; |
| 42 | Mumford River | Lackey Dam | | | | | | |
| 43 | Mumford River | Northbridge Middle School | | | | | | Aesthetics - turbidity |
| 44 | Mumford River | Downstream @Depot Street | | | | | | water appearance, |
| | unnamed tributary | Whitin Reservoir Outlet | | | | | | water odor & visual |
| | Centerville Brook*cwf | West Street | | | | | | assesments |
| | Cook Allen Brook cwf | Upstream of bridge/Johnson R | d | | | | | Temp temperature |
| 48 | West River ^{*cwf} | Hartford Avenue | | | | | | DO - dissolved |
| 49 | West River ^{*cwf} | Pleasant and Glen | | | | | | % Sat dissolved |
| 50 | West River ^{*cwf} | Mendon Road | | | | | | oxygen % saturation |
| | West River ^{*cwf} | Under Rte. 16 bridge | | | | | | Nutrients - nitrate & |
| 52 | Miscoe Brook cwf | Merriam Road | | | | | | orthophosphate |
| 53 | Warren Brook cwf | Fowler Road Bridge | | | | | | |
| | Center Brook cwf | Mendon Road | | | | | | |
| | Meadow Brook cwf | Blackstone St. Bridge | | | | | | |
| | Emerson Brook cwf | Above Quaker Highway | | | | | | |
| 57 | Bacon Brook*cwr | Balm of Life Springs Road | | | | | | |

April 2017

^{** =} site experienced 1 or more no-flow conditions # = site experienced more than 2 missed sampling events



^{*}cwf = designated cold water fishery

Blackstone River Coalition Watershed-wide Volunteer Water Quality Monitoring Program Report Card for 2016 Monitoring Season

| map | | | | | | | Nutrient |
|-----|-----------|---------------|------------|-------|----|--------|----------|
| # | WaterBody | Site Location | Aesthetics | Temp. | DO | % Sat. | s |

| | TRIBUTARIES continued | | | | | | | |
|----|-------------------------------|-------------------------|--|--|--|--|--|--|
| 58 | Mill River | Fitzgerald Street | | | | | | |
| 59 | Mill River | Mill Street | | | | | | |
| 60 | Mill River | Hartford Avenue East | | | | | | |
| 61 | Mill River | Park Street Valati Park | | | | | | |
| 62 | Mill River | Privilege Street | | | | | | |
| 63 | Clear River cwf | RI 102 | | | | | | |
| 64 | Chepachet River *cwf | Gazza Road | | | | | | |
| 65 | Tarkiln Brook | Tarkiln Road | | | | | | |
| 66 | Branch River | Rte. 146A/Great Road | | | | | | |
| 67 | Cherry Brook | Olo Street | | | | | | |
| 68 | Crookfall Brook cwf | Sayles Hill Road | | | | | | |
| 69 | Mussey Brook | New River Road | | | | | | |
| 70 | Sneech Brook cwf | Albion Road | | | | | | |
| | Monastery Brook | Mendon Road | | | | | | |
| 72 | Peters River*cwf | Paine Street | | | | | | |
| | Sylvys Brook | Grants Mill Road | | | | | | |
| | Robin Hollow Pond | Dexter Street | | | | | | |
| 75 | Millers River ^{*cwf} | Hines Road | | | | | | |

KEY TO COLOR CODES

Excellent Good Fair Poor

Categories

(Each category is derived from the combination of the following factors)

Aesthetics - turbidity, water appearance, water odor & visual assesments

Temp. - temperature **DO** - dissolved % Sat. - dissolved oxygen % saturation Nutrients - nitrate & orthophosphate

April 2017

*cwf = designated cold water fishery

^{# =} site experienced more than 2 missed sampling events



^{** =} site experienced 1 or more no-flow conditions